



CARFAX History-Based Value

2013 HYUNDAI GENESIS 2.0T

VIN: KMHHT6KDXDU112988

COUPE

2.0L I4 F DOHC 16V

GASOLINE

REAR WHEEL DRIVE



History events affecting this vehicle's value



No Accidents
Reported



1-Owner
Vehicle



Service
History

\$15,520

CARFAX History-Based Retail Value

Assumptions

Trim:	2.0T
Current Condition:	Excellent condition
Zip Code:	20158
Mileage:	53,871 miles
Color:	Red exterior

Please contact the dealer to update the assumptions for this vehicle.

This CARFAX History-Based Value is based only on information supplied to CARFAX and available as of 04/12/2018 at 3:07PM EST. Other information that may affect the value of the vehicle may not have been reported to CARFAX. To learn more, please click here .

© 2018 CARFAX, Inc., a unit of IHS Inc. All rights reserved.


Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838.

This CARFAX Vehicle History Report provided free of charge by:



Auto Link
101 E Colonial Hwy
Hamilton, VA 20158
540-338-5465

SHOW ME THE CARFAX™



CARFAX® Vehicle History Report™

US \$39.99

An independent company established in 1986

Vehicle Information:

2013 HYUNDAI GENESIS 2.0T
VIN: KMHHT6KDXDU112988
COUPE
2.0L I4 F DOHC 16V
GASOLINE
REAR WHEEL DRIVE

Standard Equipment | Safety Options

CARFAX Report Provided By:

Auto Link
101 E Colonial Hwy
Hamilton, VA 20158
540-338-5465
www.autolinkonline.net



No accidents reported to CARFAX



No other damage reported to CARFAX



CARFAX 1-Owner vehicle



7 Service history records



Last owned in Maryland



42,036 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/12/18 at 3:48:25 PM (EDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Ownership History

The number of owners is estimated

Owner 1

Year purchased	2015
Type of owner	---
Estimated length of ownership	3 yrs. 3 mo.
Owned in the following states/provinces	Maryland
Estimated miles driven per year	16,551/yr
Last reported odometer reading	42,036



CARFAX Title History

CARFAX guarantees the information in this section

Owner 1

Salvage Junk Rebuilt Fire Flood Hail Lemon	Guaranteed No Problem
Not Actual Mileage Exceeds Mechanical Limits	Guaranteed No Problem



GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. [Register](#) | [View Terms](#) | [View Certificate](#)

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.

No Issues Reported

Structural Damage

No structural damage reported to CARFAX.

No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.

No Issues Reported

Odometer Check

No indication of an odometer rollback.

No Issues Indicated

Accident / Damage

No accidents or damage reported to CARFAX.

No Issues Reported

Manufacturer Recall

Check with an authorized Hyundai dealer for any open recalls.

No Recalls Reported

Basic Warranty

[Original warranty](#) estimated to have 21 months or 17,964 miles remaining.

Warranty Active

CARFAX Detailed History

[Glossary](#)

Owner 1

Purchased: 2015
Where: Maryland
Est. miles/year: 16,551/yr
Est. length owned: 1/10/15 - present
(3 yrs. 3 mo.)

Date:	Mileage:	Source:	Comments:
10/31/2013		Hyundai Motor America	Vehicle manufactured and shipped to Maryland Original Manufacturer's Suggested Retail Price: \$26,645 Tsukuba Red exterior Black interior
12/31/2013	16	Len Stoler Ford Hyundai Owings Mills, MD 410-356-7000 lenstoler.com	Pre-delivery inspection completed
12/31/2013		Len Stoler Group lenstoler.com	Vehicle offered for sale
02/25/2014		Len Stoler Ford Hyundai Owings Mills, MD 410-356-7000 lenstoler.com	Vehicle offered for sale
01/10/2015		Len Stoler Lexus Owings Mills, MD 410-581-7000 lenstolerluxurycolle	Vehicle sold

ction.com			
01/10/2015		Maryland Motor Vehicle Dept. Jarrettsville, MD Title #46442065	Title or registration issued First owner reported Loan or lien reported
01/17/2015	265	Len Stoler Ford Hyundai Owings Mills, MD 410-356-7000 lenstoler.com	Interior trim repaired
03/24/2015	2,315	Len Stoler Ford Hyundai Owings Mills, MD 410-356-7000 lenstoler.com	Sound system component installed
04/10/2015		Len Stoler Ford Hyundai Owings Mills, MD 410-356-7000 lenstoler.com	Vehicle serviced
06/01/2015	5,258	Keene Dodge Chrysler Jeep Jarrettsville, MD 410-557-8002 keenedodge.com	Tire repaired
12/08/2016		Maryland Motor Vehicle Dept. Jarrettsville, MD Title #46442065	Registration issued or renewed
07/25/2017	41,760	#1 Cochran Hyundai of South Hills Pittsburgh, PA 412-343-3200 cochran.com	Vehicle serviced
07/25/2017	42,036	Bel Air Nissan Bel Air, MD 877-920-5634 belairnissan.com	Turbocharger replaced/repaired Drivability/performance checked
08/02/2017		Maryland Inspection Station Bel Air, MD	Passed emissions inspection

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

[View Full Glossary](#)

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Follow Us: [facebook.com/CARFAX](https://www.facebook.com/CARFAX) [@CarfaxReports](https://twitter.com/CarfaxReports) [CARFAX on Google+](https://www.google.com/+CARFAX)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX®

© 2018 CARFAX, Inc., a unit of IHS Markit. All rights reserved.

Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838.

4/12/18 3:48:25 PM (EDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2013 HYUNDAI GENESIS vehicle (VIN: KMHHT6KDXDU112988), which is based on information supplied to CARFAX and available as of 4/12/18 at 3:48 PM (EDT).

Customer Signature

Date

Dealer Signature

Date

Auto-**LINK** *Connecting Customers With Quality!*

2013 HYUNDAI GENESIS COUPE 2.0T 2DR

Standard Equipment For This Vehicle Type When Newly Manufactured:

----- INTERIOR FEATURES -----

6-Speaker Audio System
Autonet 170-Watt AM/FM/CD/MP2 Stereo
Auxiliary Power Points
Bluetooth Hands-Free Phone System
Cloth Upholstery
Day/Night Rearview Mirror
iPod/USB Audio Input
Manual Air Conditioning/Heater
Power Door Locks
Power Fuel Filler Door Release
Power Remote Trunk Release
Power Windows w/Auto-Up/Down Windows
Rear Window Defroster w/Timer
Tilt/Telescoping Steering Wheel

----- EXTERIOR FEATURES -----

Body Side Reinforcements
Halogen Projector Automatic Headlights
Power Exterior Mirrors
Remote Keyless Entry w/Panic Button
Variable Intermittent Windshield Wiper/Washer

----- ENGINEERING FEATURES -----

4-Wheel Anti-Lock Disc Brakes
Brake Assist
Electronic Brake Force Distribution
Electronic Stability Control & Traction Control
Hydraulic Rack & Pinion Steering
Tachometer

Tire Pressure Monitoring System

Turbo Boost Gauge

----- SAFETY FEATURES -----

Anti-Theft System
Driver/Front Passenger Frontal Airbags
LATCH Child Safety Seat Anchors
Side Curtain Airbags
Side-Impact Seat-Mounted Airbags

Engine: 2.0L Turbo DOHC 16V I-4
Trans: 8-Speed Automatic
VIN Number: KMHHT6KDXDU112988
Stock No.: D112988
Odometer: 53,871
Ext. Color: TSUKUBA RED
Int. Color: Black
Wheelbase: 111.0
Length: 182.3
Height: 54.5
Width: 73.4
Seating Capacity:
Fuel Capacity: 17.2

Named a 2013 AutoPacific Vehicle Satisfaction Award winner * Named among the 10 Best Sedans in its price class by Kelley Blue Book for 2012 * Car And Driver reports the Genesis Coupe inspires passion, begs you to drive it and temps you to stare at it after it's parked * Car And Driver credits Genesis Coupe with value, performance, refinement and style * Motor Trend Ultimate Guide considers Genesis Coupe a competitor capable of taking on the American retro pony cars *

AUTO LINK, INC.
101 East Colonial Highway
Hamilton, VA 20158
540-338-5465

Our Price

\$14,420.00

CITY MPG **20** FUEL ECONOMY INFORMATION HWY MPG **31**



www.autolinkonline.net

Mon-Thurs 9-5 | Sat 9-5
Friday & Sunday by Appointment

Call Today! 540-338-LINK (5465)

IT IS THE RESPONSIBILITY OF THE BUYER TO ADDRESS ANY AND ALL DIFFERENCES BETWEEN INFORMATION ON THIS LABEL AND THE ACTUAL VEHICLE AND/OR ANY WARRANTIES OFFERED PRIOR TO THE SALE OF THIS VEHICLE. Data on this label is compiled from publicly available sources believed by the publisher to be reliable. The publisher assumes no responsibility for errors and/or omissions in the compilation of this data, and makes no representations, expressed or implied, to any actual or prospective purchaser of this vehicle as to the condition of the vehicle, ownership, vehicle history, listed equipment/accessories, price or warranties. Fuel economy estimates are for newly manufactured vehicles. Actual fuel economy may vary with driving conditions, vehicle condition/age. See dealer for details. Copyright 2005 TWD. www.windowstickers.biz Printed in U.S.A.

CALL 1-262-240-9707 TO RE-ORDER THIS FORM

2013 HYUNDAI GENESIS COUPE 2.0T 2DR

Engine: 2.0L Turbo DOHC 16V I-4
 Trans: 8-Speed Automatic
 VIN No.: KMHHT6KDXDU112988
 Stock No.: D112988
 Odometer: 53871
 Interior Color: Black
 Exterior Color: TSUKUBA RED
 Wheelbase: 111.0
 Length: 182.3
 Width: 73.4
 Height: 54.5
 Seats:
 Fuel Capacity: 17.2

Named a 2013 AutoPacific Vehicle Satisfaction Award winner * Named among the 10 Best Sedans in its price class by Kelley Blue Book for 2012 * Car And Driver reports the Genesis Coupe inspires passion, begs you to drive it and tempts you to stare at it after it's parked * Car And Driver credits Genesis Coupe with value, performance, refinement and style * Motor Trend Ultimate Guide considers Genesis Coupe a competitor capable of taking on the American retro pony cars *

Standard Equipment For This Vehicle Type When Newly Manufactured:

----- INTERIOR FEATURES -----

6-Speaker Audio System
 Autonet 170-Watt AM/FM/CD/MP2 Stereo
 Auxiliary Power Points
 Bluetooth Hands-Free Phone System
 Cloth Upholstery
 Day/Night Rearview Mirror
 iPod/USB Audio Input
 Manual Air Conditioning/Heater
 Power Door Locks
 Power Fuel Filler Door Release
 Power Remote Trunk Release
 Power Windows w/Auto-Up/Down Windows
 Rear Window Defroster w/Timer
 Tilt/Telescoping Steering Wheel

----- EXTERIOR FEATURES -----

Body Side Reinforcements
 Halogen Projector Automatic Headlights
 Power Exterior Mirrors
 Remote Keyless Entry w/Panic Button
 Variable Intermittent Windshield Wiper/Washer

----- ENGINEERING FEATURES -----

4-Wheel Anti-Lock Disc Brakes
 Brake Assist
 Electronic Brake Force Distribution
 Electronic Stability Control & Traction Control
 Hydraulic Rack & Pinion Steering
 Tachometer
 Tire Pressure Monitoring System
 Turbo Boost Gauge

----- SAFETY FEATURES -----

Anti-Theft System
 Driver/Front Passenger Frontal Airbags
 LATCH Child Safety Seat Anchors
 Side Curtain Airbags
 Side-Impact Seat-Mounted Airbags

Vehicle Facts: Hyundai Genesis simplifies the lineup for 2013 with the elimination of the 4.6-liter engine, and by making the 5.0-liter engine available only on the Spec-R model * The 5.0-liter R-Spec Direct Injection V8 is the most powerful Hyundai engine ever with 429 horsepower * The Lambda 3.8-liter V6 engine features Direct Injection technology for 15 percent improved output (333 HP) with improved fuel economy and emissions * An in-house-developed eight-speed automatic transmission is featured * Hyundai Genesis 3.8 is powered by a 3.8-liter DOHC 24-valve CVVT V6 engine rated at 333 HP at 6400 RPM with a torque rating of 291 lbs.-ft. at 5100 RPM * Hyundai Genesis 5.0 Spec-R is powered by a 5.0-liter DOHC 24-valve CVVT V6 engine rated at 429 HP at 6400 RPM with a torque rating of 376 lbs.-ft. at 5000 RPM * * REASONS TO BUY: Direct injection technology has been added to models with the Lambda 3.8-liter V6 engine for 15 percent improved output and improved fuel economy and emissions; in addition, peak torque rises from 264 lb.-ft. to 291 lb.-ft., a generous increase of 27 lb.-ft. from the same 3.8 liters * Genesis 5.0 R-Spec model employ a new Tau V8 engine producing 429 horsepower at 6,400 rpm and 376 lb. ft. of torque at 5,000 rpm -- this Tau V8 represents the most powerful Hyundai engine ever, with a higher specific output than its normally-aspirated premium luxury competitors * The 5.0-liter engine's cylinder bore was increased from 92 mm to 96 mm over the 4.6-liter bore for a total displacement of 5.0 liters and direct injection technology has been added * The high-pressure direct injection system (over 2200 psi), dramatically increases power and torque while reducing fuel consumption and emissions for models with the 5.0-liter Tau V8 engine * Models with the 5.0-liter Tau V8 engine have a compression ratio that has been increased from 10.4 to 11.5:1 for greater thermal efficiency and output, along with a revised bed plate for improved block rigidity and lower NVH as well as camshaft carriers and a roller timing chain to improve valvetrain stability * R-Spec models include a more aggressive chassis tuning, matching its corresponding powertrain enhancements for optimal dynamic balance; for enhanced body roll control, rear stabilizer bars are a hollow design and diameter has increased from 18 mm to 19 mm over the 4.6 model * An in-house-developed eight-speed automatic transmission with SHIFTRONIC adds benefits in acceleration and efficiency; internal engineering tests estimate this eight-speed transmission to be six percent more efficient at transferring power than the former 6-speed automatic * Hyundai engineers have refined the 3.8 and 4.6 model suspension damping calibrations; these precise adjustments serve to minimize the traditional compromises between handling precision and ride comfort * Body roll control for the 3.8 model is enhanced, with the rear stabilizer bar diameter increasing from 17 mm to 18 mm *

Our Price

\$14,420.00

AUTO LINK, INC.
 101 East Colonial Highway
 Hamilton, VA 20158
 540-338-5465



ANY AND ALL DIFFERENCES BETWEEN THE INFORMATION PRESENTED ON THIS DOCUMENT AND THE ACTUAL VEHICLE ITSELF AND/OR ANY WARRANTIES OFFERED MUST BE ADDRESSED PRIOR TO THE SALE OF THIS VEHICLE. Data, specifications, and equipment information shown are compiled from publicly available sources believed by the publisher to be reliable. Data is subject to change without notice. The publisher assumes no responsibility for errors or omissions in the compilation of this data. Vehicle Information Sheets are prepared by the dealer solely for the dealership's use and convenience. The publisher makes no representations, express or implied, to any actual or prospective buyer of the vehicle as to the existence, description or condition of the vehicle, listed equipment, price or warranties. Fuel economy estimates are for newly manufactured vehicles. Fuel economy may vary depending on driving conditions and vehicle age/condition. See dealer for details. Copyright 2007 TWD.

BUYERS GUIDE

IMPORTANT: Spoken promises are difficult to enforce. Ask the dealer to put all promises in writing. Keep this form.

HYUNDAI	GENESIS COUPE 2.0T 2DR	2013	KMHHT6KDXDU112988
VEHICLE MAKE	MODEL	YEAR	VEHICLE IDENTIFICATION NUMBER (VIN)

WARRANTIES FOR THIS VEHICLE:

AS IS - NO DEALER WARRANTY

THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE.

DEALER WARRANTY

- FULL WARRANTY.
- LIMITED WARRANTY. The dealer will pay ___% of the labor and ___% of the parts for the covered systems that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions, and the dealer's repair obligations. *Implied warranties* under your state's laws may give you additional rights.

SYSTEMS COVERED:

DURATION:

NON-DEALER WARRANTIES FOR THIS VEHICLE:

- MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired on some components of the vehicle.
- MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.
- OTHER USED VEHICLE WARRANTY APPLIES.
- Ask the dealer for a copy of the warranty document and an explanation of warranty coverage, exclusions, and repair obligations.
- SERVICE CONTRACT. A service contract on this vehicle is available for an extra charge. Ask for details about coverage, deductible, price, and exclusions. If you buy a service contract within 90 days of your purchase of this vehicle, *implied warranties* under your state's laws may give you additional rights.

ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS. For information on how to obtain a vehicle history report, visit ftc.gov/usedcars. To check for open safety recalls, visit safercar.gov. You will need the vehicle identification number (VIN) shown above to make the best use of the resources on these sites.

SEE OTHER SIDE for important additional information, including a list of major defects that may occur in used motor vehicles.

Si el concesionario gestiona la venta en español, pídale una copia de la Guía del Comprador en español.

INSPECTION CERTIFICATION VIRGINIA STATE POLICE

Date: 04/20/2018

Sticker Number: W5867687

Station: 4071 - AUTO LINK, INC.

Inspector: 1446 - LYLES, JOEL W

License No:

VIN: KMHHT6KDXDU112988

Make: HYUNDAI

Year Built: 2013

Body Type: CAR 2 DOOR

Odometer Reading: 53925

Inspection Fee: \$ 16.00

Related Charges: \$ 0.00

Total Charges: \$ 16.00

Wheels Inspected:	RF X	LF X	RR X	LR X
-------------------	------	------	------	------

EQUIPMENT INSPECTED	O.K.	ADJUST	INSTALL	REMOVE
BRAKES	X			
HEADLIGHTS	X			
SIGNAL LIGHTS	X			
OTHER LIGHTS	X			
STEERING	X			
SUSPENSION	X			
EXHAUST SYSTEM	X			
FUEL SYSTEM	X			
TIRES	X			
HOOD LATCH	X			
EMISSION CONTROL	X			
WINDSHIELD	X			
WINDSHIELD WIPERS	X			
OTHER GLASS	X			
MIRROR	X			
DOORS	X			
SEATS	X			
SEAT BELTS	X			
FLOOR PAN	X			
DEFROSTER	X			
HORN	X			

Printed: 04/21/2018 06:27 PM ID: 85752082

THIS RECEIPT SHOULD BE KEPT IN THE VEHICLE AT ALL TIMES WHILE THE VEHICLE IS BEING OPERATED.



**COMMONWEALTH OF VIRGINIA
VEHICLE EMISSIONS INSPECTION REPORT**



Test Date/Time: 04/12/2018 @ 14:13:47
Inspection Type: Initial

OVERALL TEST RESULTS: PASS

Year: 2013		Make: HYUNDAI		Model: GENESIS COUPE		
VIN: KMHHT6KDXDU112988		Engine Size: 2.0 L		Cylinders: 4		
GVWR: 4343		ETW: N/A		Mileage: 53,891		
TSI TAILPIPE EMISSIONS INSPECTION				EMISSIONS CONTROL SYSTEM INSPECTION		
	2500 RPM			Idle		
	Limit	Reading	Result	Limit	Reading	Result
HC ppm	N/A	N/A	N/A	N/A	N/A	N/A
CO %	N/A	N/A	N/A	N/A	N/A	N/A
NO ppm	N/A	N/A	N/A	N/A	N/A	N/A
	RPM	N/A	N/A	RPM	N/A	N/A
	Dilution %	N/A	N/A	Dilution %	N/A	N/A
VISIBLE SMOKE INSPECTION: PASS				ON BOARD DIAGNOSTIC SYSTEM INSPECTION		
				Air Injection System: N/A		
				Exhaust Gas Recirculation System: N/A		
				Positive Crankcase Ventilation System: N/A		
				Catalytic Converter: PASS		
				Fuel Evaporative System: N/A		
				Thermostatic Air Cleaner System: N/A		
				OBD Malfunction Indicator Lamp: PASS		
				OBD Diagnostic Trouble Codes: PASS		

PLEASE RETAIN THIS DOCUMENT FOR YOUR RECORDS

Results of the emissions inspection for this vehicle will be transmitted electronically to DMV, usually within 24 hours.
You may now register this vehicle for a period of up to two (2) years.

EMISSIONS INSPECTION STATION			
STATION NAME: Progressive Automotive	REPORT NUMBER: 720		
ADDRESS: 11 E Colonial Hwy	STATION NUMBER: 1328		
PHONE: 5403381857	ANALYZER NUMBER: VA424511		
INSPECTOR NAME: Welty, Mark W.	SOFTWARE VERSION: 15.01.20		

<p align="center">VEHICLE EMISSIONS INSPECTION QUESTIONS</p> <p>For additional information, please contact the Department of Environmental Quality, Air Check Virginia (703) 583-3900 or (800) 275-3844 www.deq.virginia.gov/Programs/AirCheckVirginia.aspx</p>	<p>Inspector's Signature</p>
---	------------------------------

	Transaction ID Number: AA219636	Version: 3.02
--	--	---------------

AUTO LINK INC.
 101 EAST COLONIAL HWY.
 PO. BOX 98
 HAMILTON, VA 20158

Invoice

Date	Invoice #
4/26/2018	371

Bill To
AUTO LINK INC. 101 EAST COLONIAL HWY. HAMILTON, VA.20158

Ship To

P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
			4/26/2018			

Quantity	Item Code	Description	Price Each	Amount
1	PARTS	OIL FILTER WS0229WS	6.98	6.98T
5.7	PARTS	TE 101WS MOBIL 1 SYNTHETIC OIL	7.50	42.75T
1	PARTS	WHEEL KEY LOCK WS010.49SW	20.00	20.00T
1	LABOR	OIL CHANGE	35.00	35.00
1	LABOR	STATE INSPECTION	16.00	16.00
1	LABOR	DEQ EMISSIONS	28.00	28.00
1	LABOR	DETAIL /PREP/ MINOR SERVICE & OVERALL CHECK OUT - PASS	350.00	350.00
		Sales Tax	6.00%	4.18

ALL WORK HAS BEEN COMPLETED.TECH COMMENTS:VEHICLE PERFORMS EXCELLENT.

Total \$502.91

Customer Invoice
035249
11/29/2017

FIRESTONE COMPLETE AUTO CARE
FOREST HILL
608 HOAGIE DRIVE
BEL AIR, MD. 21014-1884

Service Advisor:
09 TASHA
410.420.0814

2013 HYUNDAI GENESIS COUPE 2.0T
Lic #: 1BW5511 MD Vin #: KMHHT6KDXDU112988
In: 11/29/17 1:58PM Mileage: 48,628
Out: 11/29/17 3:35PM

RETAIL SALE

Description	Rev Hist /Article #	ID	Qty	Unit Price	Extended Price	Job Total
TIRE RACK INSTALL W/TPMS - 40 & 45 SERIES (All 4)		09				86.80
6-231C TPMS KIT VS70	7012743	05TN	4	5.00	20.00	
TIRE RACK TPMS VALVE SERVICE KIT LABOR	7004008	05NS	4	N/C	N/C	
TIRE RACK INSTALLATION 40-45 SERIES & LO	7009541	05TS	4	7.50	30.00	
TIRE RACK WHEEL BALANCE LABOR	7013637	05NS	4	6.70	26.80	
INSTALLER SCRAP TIRE RECYCLING CHARGE	7084301	05TN	4	2.50	10.00	
COURTESY CHECK		09				
COURTESY CHECK	7046930	05NS	1	N/C	N/C	
STANDARD ALIGNMENT	2	01				79.99
ALIGNMENT SERVICE	7004578	05NS	1	89.99	89.99	
LBR-DISC Regional Promotion	7001639	05N	-1	10.00	-10.00	

Technician(s):
05 STEVEN

Payment History:
Visa 6424 180.54 423111
Total Tendered 180.54

Summary:

Parts	20.00
Labor	146.79
Shop Supplies	9.58
Sub-Total	176.37
Tax (6.00%)	4.17
Total	\$180.54


I have received the above goods and/or services. If this is a credit card purchase, I agree to pay and comply with my cardholder agreement with the issuer.


Customer Signature

Revision History:	Rev Amt	Init
1) 11/29/2017 03:02PM	26.84	
2) 11/29/2017 03:19PM	59.08	

All parts are new unless otherwise specified.

I verbally approved any change to the original estimate, including price or services.


Signature or Initials

While a customer's motor vehicle is on the premises of the automotive repair facility, the automotive repair facility may not be responsible for any damage to the customer's motor vehicle under specified circumstances, and that the customer should ask a representative of the automotive repair facility about the extent of its responsibility, including the extent of insurance coverage; et Manufacturer Special Policy Adjustment Programs

Federal law requires manufacturers to furnish the National Highway Traffic Safety Administration (N.H.T.S.A.) with bulletins describing any defects in their vehicles. You may obtain copies of these bulletins from either the manufacturer or N.H.T.S.A. In addition, certain consumer publications or organizations publish this information, which may be available for a fee or for free.



www.FirestoneCompleteAutoCare.com

STD FCAC LASER 7008335 - 48110392 REV 11/11



See reverse side for Warranty Information

Customer Invoice
035249
11/29/2017

FIRESTONE COMPLETE AUTO CARE
FOREST HILL
608 HOAGIE DRIVE
BEL AIR, MD. 21014-1884

Service Advisor:
09 TASHA
410.420.0814

2013 HYUNDAI GENESIS COUPE 2.0T
Lic #: 1BW5511 MD Vin #: KMHHT6KDXDU112988
In: 11/29/17 1:58PM Mileage: 48,628
Out: 11/29/17 3:35PM

RETAIL SALE

Description	Rev Hist /Article # ID	Qty	Unit Price	Extended Price	Job Total
-------------	------------------------	-----	------------	----------------	-----------



HOW ARE WE DOING?

Tell us about your experience today!
Complete a 4-minute survey for a chance to win \$500 in store services
Visit www.FirestoneSurvey.com within 4 days and enter Code 749143-035249

COMMITTED TO PROVIDING A POSITIVE CUSTOMER EXPERIENCE
www.FirestoneCompleteAutoCare.com

STD FCAC LASER 7008335 - 48110392 REV 11/11

See reverse side for Warranty Information



Courtesy Check

Inspect All Items in Top Section

Year 13 Make Hyundai Model Genesis
 VIN KMHHT6K1D1112988
MILEAGE: 48628

Eng. Size 2.0 SOHC OHV DIESEL Auto
 DOHC HYBRID Manual
 Hubcap Missing Y N Windshield Cracked Y N Scratches/Dents Y N
 Lic. # 1BW5511 State Inspection Due Month _____ Year _____

Inspect	Visual			Sched. Maint.	Why Recommended
	OK	SUG	REQ		
Wiper Blades	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Front <input type="checkbox"/> Rear
Head Lights	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Mini Lights	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Brake <input type="checkbox"/> Turn Signal <input type="checkbox"/> License Plate <input type="checkbox"/> Parking
Air Filter	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Cabin Air Filter	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
PCV Valve	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Washer Fluid	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Oil Level	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Power Str. Fluid Level	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Master Cyl. Fluid Level	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Brake Inspection
Brake Fluid Flush	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	0 10 30 100 200 300 Copper parts per million
Trans. Service Auto / Manual	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Flush <input type="checkbox"/> Pan Service
Coolant Level / Flush	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Type _____
Coolant Hoses	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Upper <input type="checkbox"/> Lower <input type="checkbox"/> Bypass <input type="checkbox"/> Heater
Belts <input type="checkbox"/> V <input type="checkbox"/> Serp	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> ALT <input type="checkbox"/> PS Belts 1 2 3 4 <input type="checkbox"/> A/C <input type="checkbox"/> AP
Battery ED-18 Test	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Good <input type="checkbox"/> Marginal <input type="checkbox"/> Replace
Battery Accessories	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Cable Ends / Cables <input type="checkbox"/> Pos <input type="checkbox"/> Neg <input type="checkbox"/> Hold Downs
Battery Gard	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Corrosion <input type="checkbox"/> Preventive

Tires and Tire Maintenance						
Tire Size:				Speed Rating	Run Flat	Y N
F					<input type="checkbox"/>	<input type="checkbox"/>
R					<input type="checkbox"/>	<input type="checkbox"/>
Inspect	Visual			Tread Depth 32nds		FWD <input type="checkbox"/> RWD <input type="checkbox"/> 4WD/AWD <input type="checkbox"/>
	OK	SUG	REQ	Outer	Inner	
Left Front						
PSI In:	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Edgewear <input type="checkbox"/> Cracking
PSI Out:	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Cupping <input type="checkbox"/> Nails
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Cuts <input type="checkbox"/> Repairable
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Irregularity <input type="checkbox"/> Non-Repairable
Right Front						
PSI In:	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Edgewear <input type="checkbox"/> Cracking
PSI Out:	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Cupping <input type="checkbox"/> Nails
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Cuts <input type="checkbox"/> Repairable
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Irregularity <input type="checkbox"/> Non-Repairable
Right Rear						
PSI In:	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Edgewear <input type="checkbox"/> Cracking
PSI Out:	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Cupping <input type="checkbox"/> Nails
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Cuts <input type="checkbox"/> Repairable
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Irregularity <input type="checkbox"/> Non-Repairable
Left Rear						
PSI In:	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Edgewear <input type="checkbox"/> Cracking
PSI Out:	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Cupping <input type="checkbox"/> Nails
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Cuts <input type="checkbox"/> Repairable
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Irregularity <input type="checkbox"/> Non-Repairable
Spare						
PSI In:	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Edgewear <input type="checkbox"/> Cracking
PSI Out:	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Cupping <input type="checkbox"/> Nails
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Cuts <input type="checkbox"/> Repairable
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Irregularity <input type="checkbox"/> Non-Repairable
Tire Maintenance	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Rotation <input type="checkbox"/> Balance
Alignment Check	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Maintenance <input type="checkbox"/> Tire Wear

Complete Vehicle Inspection

In Addition to The Above Inspect All Items Below

Inspect	Visual			Sched. Maint.	Why Recommended
	OK	SUG	REQ		
Start / Charge Test	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Belt Tensioner	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Spark Plugs	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Fuel Filter	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Fuel System Service	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Ignition Wires	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Valve Cover Gasket	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Power Steering Hose	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Pressure <input type="checkbox"/> Return
Timing Belt	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	

Brakes						ABS	YES	NO
Pads greater than 6mm (Disc) or Shoes greater than 2.4mm (Drum)								
Pads greater than 3mm or less than 6mm (Disc) or Shoes greater than 1.6mm or less than 2.4mm (Drum) Document vehicle specific measurements & minimum specifications below								
Pads less than 3mm (Disc) or Shoes less than 1.6mm (Drum) Document vehicle specific measurements & minimum specifications below								
LF Pad	LF Rotor / RF Rotor				RF Pad			
<input checked="" type="checkbox"/>	Actual Meas.	<input checked="" type="checkbox"/>	Actual Meas.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>	Machine To	<input checked="" type="checkbox"/>	Machine To	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>	Discard At	<input checked="" type="checkbox"/>	Discard At	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>			
LR Pad / Shoe	Drum LF Rotor / Drum RR Rotor				RR Pad / Shoe			
<input checked="" type="checkbox"/>	Actual Meas.	<input checked="" type="checkbox"/>	Actual Meas.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>	Machine To	<input checked="" type="checkbox"/>	Machine To	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>	Discard At	<input checked="" type="checkbox"/>	Discard At	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>	Rear Clean / Adj	<input checked="" type="checkbox"/>						
<input checked="" type="checkbox"/>	Brake Hose(s)	<input checked="" type="checkbox"/>						
<input checked="" type="checkbox"/>	Parking Cables	<input checked="" type="checkbox"/>						
<input checked="" type="checkbox"/>	Other Brake Services	<input checked="" type="checkbox"/>	Hardware	Caliper	Wheel Cylinder	Repack		

Exhaust					
Exhaust System	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Intermediate Pipe <input type="checkbox"/> Muffler <input type="checkbox"/> Tailpipe

Steering and Suspension					
U-Joint	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Front <input type="checkbox"/> Rear
Idler/Pitman Arm	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Idler <input type="checkbox"/> Pitman
Center Link	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Bushings	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Control Arm <input type="checkbox"/> Sway Bar <input type="checkbox"/> Front <input type="checkbox"/> Rear
Link Pins	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Front <input type="checkbox"/> Left <input type="checkbox"/> Right <input type="checkbox"/> Rear <input type="checkbox"/> Left <input type="checkbox"/> Right
Tie Rod Ends	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> L Out <input type="checkbox"/> L In <input type="checkbox"/> R In <input type="checkbox"/> R Out <input type="checkbox"/> Sleeve(s)
Ball Joints	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> L Upper <input type="checkbox"/> R Upper <input type="checkbox"/> L Lower <input type="checkbox"/> R Lower Spec Actual
Rack & Pinion Assembly	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
CV Boots	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> L Out <input type="checkbox"/> L In <input type="checkbox"/> R In <input type="checkbox"/> R Out
CV Joints	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> L Out <input type="checkbox"/> L In <input type="checkbox"/> R In <input type="checkbox"/> R Out
Struts	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Front <input type="checkbox"/> Rear <input type="checkbox"/> Left <input type="checkbox"/> Right <input type="checkbox"/> Left <input type="checkbox"/> Right
Shocks	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Front <input type="checkbox"/> Rear <input type="checkbox"/> Left <input type="checkbox"/> Right <input type="checkbox"/> Left <input type="checkbox"/> Right

Notes: Align check - Front inner edgewear

#05

OK *Checked & acceptable	Repair / Replacement Suggested 1) Close to end of useful life 2) Address customer request / need / convenience 3) Comply with manufacturer recommendation 4) Technician recommendation from experience	Repair / Replacement Required A) No longer performs intended purpose B) Does not meet design specification C) Missing
------------------------------------	---	---

STEP 5 INSPECTED BY _____ STEP 7 RE-INSPECTED BY _____

FIRESTONE

Work Order: R000001
VIN: KMHHT6KDXDU112988
Year: 13
Date: 11/29/17 3:47 PM



KMHHT6KDXDU112988

Hyundai 2013-16 Genesis Coupe

Front : Left

Actual	Before	Specified Range
-1.15°	-1.15°	-1.20° -0.20°
		6.95° 7.95°
0.14°	0.12°	0.04° 0.24°

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1.30°	-1.30°	-1.20° -0.20°
		6.95° 7.95°
0.12°	0.23°	0.04° 0.24°

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0.15°	0.20°	-0.50° 0.50°
		-0.50° 0.50°
0.26°	0.34°	0.08° 0.48°

Rear : Left

Actual	Before	Specified Range
-1.70°	-2.05°	-2.00° -1.00°
0.11°	0.11°	-0.02° 0.18°

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1.80°	-1.90°	-2.00° -1.00°
0.10°	-0.16°	-0.02° 0.18°

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0.05°	-0.15°	-0.50° 0.50°
0.21°	-0.05°	-0.04° 0.36°
0.01°	0.13°	

BEL AIR NISSAN/HYUNDAI

1506 BELAIR ROAD

BEL AIR, MARYLAND 21014

BEL AIR BALTIMORE
(410) 838-0222 (410) 879-1133

www.jonesjunction.com



SERVICE & PARTS HOURS:



0103IHYS768573

CUSTOMER NO. 1864420	ADVISOR SHEENA COLBERT	330474	TAG NO.	INVOICE DATE 07/31/17	INVOICE NO. HYCS768573
LABOR RATE	LICENSE NO.	MILEAGE 42,036	COLOR /	STOCK NO.	
YEAR / MAKE / MODEL 13/HYUNDAI/GENESIS COUPE/2DR 2.0 MT			DELIVERY DATE	DELIVERY MILES	
VEHICLE I.D. NO. K M H H T 6 K D X D U 1 1 2 9 8 8			SELLING DEALER NO.	PRODUCTION DATE	
F.T.E. NO.		P.O. NO.	R.O. DATE 07/25/17		
COMMENTS					

MO: 42036

LABOR & PARTS
1 10HYZ

DRIVEABILITY TECH(S):330506 **WARRANTY**
CUSTOMER STATES WHEN STEPPING ON GAS PEDAL THE FIRST 10 PERCENT OF PRESSING PEDAL WILL ACCELERATE VEHICLE AFTER THAT IS WILL NOT ACCELERATE ANY FURTHER. UPON INSPECTION FOUND RE CIRCULATION VALVE FAULTY, ALONG WITH BOOST PRESSURE SENSOR AT DEALER IN PA TECH FOUND CODE P0299 TURBO CHARGER UNDER BOOST FOUND TURBO WHEEL HITTING COMPRESSOR HOUSING DUE TO FAILED TURBO BEARING REPLACED TURBO CHARGER

LIMITED WARRANTY
SERVICE/PARTS ARE WARRANTED 12,000 MILES OR 12 MONTHS, WHICHEVER OCCURS FIRST. THIS WARRANTY DOES NOT EXCLUDE OR MODIFY ANY OTHER WARRANTY PRESCRIBED BY LAW.

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
JOB # 1	4		28233-2GTA1	STUD		WARRANTY
JOB # 1	1		28535-2C610	GASKET		WARRANTY
JOB # 1	1		28231-2C600	TURBOCHARGER		WARRANTY
JOB # 1	1		28521-2C600	GASKET-EXHAUST MA		WARRANTY
JOB # 1	2		28256-4A421	NUT		WARRANTY
					JOB # 1 TOTAL PARTS	0.00
					JOB # 1 TOTAL LABOR & PARTS	0.00

ALL PARTS INSTALLED ARE NEW OR FACTORY REBUILT UNLESS SPECIFIED OTHERWISE.

I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

MISC	CODE	DESCRIPTION	CONTROL NO	WARRANTY
JOB # 1	104	RENTAL	768573	WARRANTY
			TOTAL - MISC	0.00

TOTALS		
TOTAL LABOR	0.00	
TOTAL PARTS	0.00	
TOTAL SUBLET	0.00	
TOTAL G.O.G.	0.00	
TOTAL MISC CHG.	0.00	
TOTAL MISC DISC	0.00	
TOTAL TAX	0.00	
TOTAL INVOICE \$	0.00	

WHILE YOUR MOTOR VEHICLE IS ON THE PREMISES OF THE AUTOMOTIVE REPAIR FACILITY, THE AUTOMOTIVE REPAIR FACILITY MAY NOT BE RESPONSIBLE FOR DAMAGE TO YOUR MOTOR VEHICLE UNDER CERTAIN CIRCUMSTANCES. YOU SHOULD ASK A REPRESENTATIVE OF THE AUTOMOTIVE REPAIR FACILITY ABOUT THE EXTENT OF ITS RESPONSIBILITY, INCLUDING THE EXTENT OF THE INSURANCE COVERAGE OF THE AUTOMOTIVE REPAIR FACILITY.

* IT IS IMPORTANT TO US THAT YOU ARE 100% *
* SATISFIED WITH YOUR SERVICE EXPERIENCE. *
* NISSAN SERVICE CONTACT: DENNIS SHEPARD *
* HYUNDAI SERVICE CONTACT: JAY KENDALL *
* PHONE US AT 410-879-1133 *

X
CUSTOMER'S SIGNATURE

CUSTOMER SIGNATURE

The Reynolds and Reynolds Company. All Rights Reserved. EFRANTIS/BL/LE CC610340 Q (10/14) THE PRINTER MAKES NO WARRANTY, EXPRESS OR IMPLIED, AS TO CONTENT OR FITNESS FOR PURPOSE OF THIS FORM. CONSULT YOUR OWN LEGAL COUNSEL.

CUSTOMER #: 545086

894410

INVOICE



3200 West Liberty Ave.
Pittsburgh, PA 15216
(412) 343-3200
www.cochran.com

PAGE 1

SERVICE ADVISOR: 996954 Jordan Nardozi

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG, DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Includes data for 2013 Hyundai Genesis Coup and payment details.

Table with columns: R.O. OPENED, READY, OPTIONS, LIST, NET, TOTAL. Includes time entries for 07:43 and 14:29 on 21JUL17.

LINE OPCODE TECH TYPE HOURS
A CUSTOMER STATES WHEN STEPPING ON GAS PEDAL ONLY THE FIRST 10% OF PRESSING PEDAL WILL ACCELERATE VEHICLE. AFTER THAT IT WILL NOT ACCELERATE ANY FURTHER.

CAUSE: C
NTF00RQ0 NTF OP FOR NO DTC OR DRIVEABILITY CONCERN
6556 WH

(N/C)

FC:
PART#: 28234-2G410
COUNT: 0
CLAIM TYPE: WAR
AUTH CODE:

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00
41760 UPON INSPECTION FOUND RE CIRCULATION VALVE FAULTY, ALONG WITH BOOST PRESSURE SENSOR. VEHICLE HAS NO TURBO BOOST. CUSTOMER LIVES OUT OF STATE, PARTS NEEDED TO BE ORDERED. CUSTOMER OPTED TO DRIVE VEHICLE HOME. VEHICLE WILL STILL OPERATE, RECOMMEND USING PADDLE SHIFTERS UNTIL CUSTOMER GETS HOME AND TAKES TO LOCAL HYUNDAI DEALERSHIP FOR REPAIRS.

B PODS UNIT CONN. REWORK (TSB#16-01-042)
CAUSE: PERFORMED CAMPAIGN
60C071R0 POS UNIT CONN. REWORK
6556 WH

(N/C)

FC: PART#: COUNT:
CLAIM TYPE: CPM
AUTH CODE:

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00
41760 recall installed zip tie on connector

C Hyundai Walk Around Multi Point Inspection
MPI Hyundai Walk Around Multi Point Inspection
6556 CPM

0.00 0.00

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO THE OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.

STATEMENT OF DISCLAIMER
The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Table with columns: DESCRIPTION, TOTALS. Rows include LABOR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, MISC. CHARGES, TOTAL CHARGES, ACCOUNTS RECEIVABLE, SALES TAX, PLEASE PAY THIS AMOUNT.

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

CUSTOMER SIGNATURE

CUSTOMER #: 545086

894410

INVOICE



3200 West Liberty Ave.
Pittsburgh, PA 15216
(412) 343-3200
www.cochran.com

PAGE 2

SERVICE ADVISOR: 996954 Jordan Nardozi

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	13	HYUNDAI GENESIS COUP	KMHHT6KDXDU112988		41760/41760	T1126	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN13 DD			17:00 21JUL17		0.00	CASH	21JUL17
R.O. OPENED	READY	OPTIONS:					
07:43 21JUL17	14:29 21JUL17						
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE C:	0.00

EST: 0.00

21JUL17 07:43 SA: 996954

THANK YOU for allowing us the opportunity to serve you today at #1 Cochran Hyundai. Your COMPLETE SATISFACTION is our expectation and please let us know if for any reason we did not meet that goal. You can contact us at: feedback@cochran.com

<p>ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.</p>	STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS
	The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	LABOR AMOUNT	0.00
		PARTS AMOUNT	0.00
		GAS, OIL, LUBE	0.00
		SUBLET AMOUNT	0.00
		MISC. CHARGES	0.00
		TOTAL CHARGES	0.00
		ACCOUNTS RECEIVABLE	0.00
		SALES TAX	0.00
		PLEASE PAY THIS AMOUNT	0.00
(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	CUSTOMER SIGNATURE		

CUSTOMER COPY

Vehicle Emissions Inspection Certificate

State of Maryland

OBD Test Results

065832842



Overall Result	Valid Through	Test Verification
PASS	07-AUG-2019	BAAC F3DA

Vehicle Information						
Tag	VIN	Year	Make	Model	Wt Class	Assigned Date
1BW5511	KMHHT6KDXDU112988	2013	HYUN	GENESIS	LDGV	02-AUG-2017

Facility Information							
Station	Lane	Unit	Inspector ID	Test Number	Test Date	Start	End
8	2	3	511257	1	02-AUG-2017	07:03:00	07:04:10

Payment Information					
Test Fee	Late Fee	Total Paid	Payment Type	Tendered	Change
14.00	0.00	14.00	CREDIT	14.00	0.00

Credit Card Information				
CC Number	Type (Visa, MC, etc.)	Expiration	Transaction Code	Name On Card
3150	CREDIT	On File	H61807	On File



Credit Card Signature: **On File**

This Certificate Must Be Kept In The Vehicle

This emissions test certifies that the vehicle listed is in compliance through the "Valid Through" date shown above. Any emissions-related warning, flag, or suspension that was issued prior to the "Valid Through" date is hereby rescinded. If you sell this vehicle, you should give this certificate to the buyer. The buyer should present this certificate to the MVA when titling the vehicle to ensure the vehicle remains in compliance.

For More Information: Call -1-800-638-8347 or visit our website at <http://www.marylandmva.com>

AUTO LINK INC.

101 EAST COLONIAL HWY.
 PO. BOX 98
 HAMILTON, VA 20158

Invoice

Date	Invoice #
4/26/2018	371


Bill To
AUTO LINK INC. 101 EAST COLONIAL HWY. HAMILTON, VA.20158

Ship To

P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
			4/26/2018			

Quantity	Item Code	Description	Price Each	Amount
		2013 HYUNDAI GENESIS VIN # KMHHT6KDXDU112988 SERVICE @ 53891:		
1	PARTS	OIL FILTER WS0229WS	6.98	6.98T
5.7	PARTS	TE 101WS MOBIL 1 SYNTHETIC OIL	7.50	42.75T
1	PARTS	WHEEL KEY LOCK WS010.49SW	20.00	20.00T
1	LABOR	OIL CHANGE	35.00	35.00
1	LABOR	STATE INSPECTION	16.00	16.00
1	LABOR	DEQ EMISSIONS	28.00	28.00
1	LABOR	DETAIL /PREP/ MINOR SERVICE & OVERALL CHECK OUT - PASS	350.00	350.00
		Sales Tax	6.00%	4.18

ALL WORK HAS BEEN COMPLETED.TECH COMMENTS:VEHICLE PERFORMS EXCELLENT.	Total	\$502.91
---	--------------	----------



Angie's list

You've been
REVIEWED!

Your customer posted a review on their experience with you

Read what they said

Angie's list. 1030 E. Washington St. Indianapolis, IN 46202

Angie's List connects serious consumers searching for quality service providers. Members pay for access to providers offering the best service based on the feedback of other members.

PRSR STD
U.S. Postage
PAID
Plum Grove

2160 Stonington Ave.
Hoffman Estates, IL 60169

"I have used them for about 35 years and I think they are excellent! Their prices are reasonable, and they do excellent work! They are very pleasant people. They are professional and on time."

- Example Member Review

Read your review and learn how your FREE account can help you grow your business. Visit Business.AngiesList.com, or call 1-866-843-LIST (5478).

You've Been Reviewed!

Your customer has posted a review about you

Auto LINK

Connecting Customers with Quality!

JOEL LYLES

101 E. Colonial Hwy.
Hamilton, VA 20158
Phone: 540-338-LINK (5465)
Fax: 540-338-7218
<http://www.autolinkonline.net>